

	Type	Hits	Search Text
1	BRS	212	((ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa) same repeater\$1 same (amplif\$5 gain\$1) same wavelength\$1
2	BRS	1962544	(communication\$1 transceiv\$4 (transm\$5 same receiv\$4))
3	BRS	22778	(spac\$4 interval\$1 band\$1 cband lband) same (ghz '100ghz' 50ghz'200ghz' '150ghz')
4	BRS	141154	amplif\$5 same gain\$1
5	BRS	1350	amplif\$5 same gain\$1 same repeater\$1
6	BRS	50	S1 and S2 and S3 and S4
7	BRS	37	S1 and S2 and S3 and S5
8	BRS	20	S7 and ('c' near3 band\$2)
9	BRS	32792	((ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa amplif\$5) same channels
10	BRS	15	S8 and S10
11	BRS	15	S11 and (optic\$4 same signal\$3)
12	BRS	18	("20030210844" "20020196492" "20010028489" "20010022676" "6782205" "6417945" "6384943" "6275314" "6252688" "6252687" "6243176" "5696614" "5636046" "5612807" "5602666").pn.
13	BRS	15	("20030210844" "20020196492" "20010028489" "20010022676" "6782205" "6417945" "6384943" "6275314" "6252688" "6252687" "6243176" "5696614" "5636046" "5612807" "5602666").pn.
14	BRS	32751	((ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa amplif\$5) same amplif\$5 same channels
15	BRS	15	S14 and S16
16	BRS	3555	(wavelengths same repeater\$1 same gain\$1 same (ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa)
17	BRS	15	S17 and S18
18	BRS	1384	((ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa) near12 gain\$1
19	BRS	15	S19 and S20
20	BRS	170	(repeater\$1 near14 wavelength\$1 near14 gain\$1)
21	BRS	0	S21 and S22

22	BRS	481	(repeater\$1 same wavelength\$1 same gain\$1)
23	BRS	15	S15 and S24

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:24		
2	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 16:55		
3	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:18		
4	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:03		
5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:01		
6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:12		
7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:05		
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:02		
9	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:29		
10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:09		
11	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:25		
12	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:27		
13	US-PGPUB; USPAT	2005/01/04 17:28		
14	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:45		
15	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:48		
16	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:33		
17	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:35		
18	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:36		
19	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:36		
20	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:41		
21	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:40		

22	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:41		
23	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:48		

	Errors	Ref #
1		S1
2		S2
3		S3
4		S4
5		S5
6		S6
7		S7
8		S8
9		S10
10		S11
11		S12
12		S13
13		S14
14		S16
15		S17
16		S18
17		S19
18		S20
19		S21
20		S22
21		S23

22		S24
23		S25

	Type	Hits	Search Text
24	BRS	741	((ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa) same amplif\$5 same channels
25	BRS	14	S25 and S26
26	BRS	15	S14 and (cband ('c' near3 band\$1)) and (spac\$4 interval\$1 band\$1 cband lband) same (ghz '100ghz' 50ghz '200ghz' '150ghz')
27	BRS	5	("20030210844" "20020196492" "6782205").pn.
28	BRS	2	S30 and (Gain near7 (flat\$5 zero constant))
29	BRS	3	("20030210844" "20020196492" "6782205").pn.
30	BRS	1	"20030210844"
31	BRS	1	S32 and (repeater\$1 channels)
32	BRS	1	S33 and ((ebrium adj1 dop\$4 adj1 (fiber\$1 fibre\$1) adj1 amplif\$6) edfa) same repeater\$1
33	BRS	0	10/747970
34	BRS	0	"10747970"
35	BRS	50	S6 and (amplif\$5 same repeater\$1)
36	BRS	24	S37 and ('c' near3 band\$2)
37	BRS	1	S38 and map\$4
38	BRS	0	S38 not (S8 S37)
39	BRS	3	S38 not (S8 S39)
40	BRS	1	S32 and S1

	DBs	Time Stamp	Comments	Error Definition
24	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:46		
25	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 17:47		
26	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 18:05		
27	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 18:06		
28	US-PGPUB; USPAT	2005/01/04 18:24		
29	US-PGPUB; USPAT	2005/01/04 18:08		
30	US-PGPUB; USPAT	2005/01/04 18:25		
31	US-PGPUB; USPAT	2005/01/04 18:30		
32	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 18:41		
33	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 18:41		
34	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 18:41		
35	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:01		
36	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:02		
37	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:03		
38	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:12		
39	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/04 19:12		
40	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/01/06 11:52		

	Errors	Ref #
24		S26
25		S27
26		S28
27		S29
28		S31
29		S30
30		S32
31		S33
32		S34
33		S35
34		S36
35		S37
36		S38
37		S39
38		S40
39		S41
40		S42